

Personal Safety is Everyone's Business

To: Steve Brady

From: Campus Personal Safety Committee

Subject: Personal Safety and Campus Lighting Survey
Conducted May 06, 2003 by Campus Safety Committee

Date: June 20, 2003

The following is are observations and recommendations resulting from the annual survey of Campus by the Campus Personal Safety Committee.

1. Three exterior lights on Silverman Hall were found out. This was subsequently reported by Public Safety and a map provided to the MOC Center of their locations.
2. There is a light out above the overhead door in the B-4 Lot.
3. A light is needed over the double doors in the Rear Courtyard to Weiskotten Hall which is focused down over the doors.
4. The committee after several years of reporting the condition still feels that there is not enough lighting on the east side of Weiskotten Hall New Library and again recommends lighting in this area. Some type of flood lighting should be installed on the east side of the New Library addition.
5. Pole Lights along the curved sidewalk in the front courtyard to Weiskotten Hall, several are enveloped by trees and effectiveness significantly reduced. Two poles were found to have been taken down and the electrical wiring was covered by only a bucket on the ground and the committee members believe it poses a hazard.
6. Iron grates on the north side of the courtyard at Weiskotten Hall were unsecured and allow access below to the workshop whose door was propped open and light on. Locks should be affixed to the grates.

7. The first light pole along Memorial Drive as you enter from the east at Memorial Drive and Irving at Weiskotten Hall is out.
8. Gross Anatomy along Memorial Drive, which is still under construction was found insecure. A piece of plywood was set up over the doorway and only a cinder block supported it. Anyone passing by could have entered the area. A window there was also found unlocked. The contractor should be advised to secure the area more effectively. Public Safety was contacted to see if they could secure the area and generate a report.
9. There is a light out underneath the 7th floor tunnel which is used to illuminate this area. This condition was reported by Public Safety for repair or replacement. A light was also found out on the north side of the anatomy lab and was also reported by Public Safety for repair. The committee strongly recommends reinstallation of the chain link fence under the 7th floor tunnel once construction in the area allows.
10. There is a significant amount of garbage in the pit just past the smoke room on the left going north. Garbage includes rotting foodstuffs. The area needs to be cleaned out.
11. On Memorial Drive in the area of the Concentrated Care Center (East Wing) on the North side of the road and abutting the building there is a large pit. A grate which leads to the ladder to enter the pit was found unlocked. A padlock needs to be installed on the grate.
12. The Trees on the North side of 710 Irving Ave facing the parking lot need to be trimmed again to enable the lights to illuminate the area. The lights were ineffective. The committee would like to suggest that a light be installed on the Boiler Room Tower at the North West corner of the lot which would be focused into the lot to illuminate it more effectively. A light was found out on 710 and subsequently reported to the MOC Center and an location map provided. A light was also found to be out on the rear stairwell to 714 Irving and Public Safety made notification for repair.
13. The committee still believes the lighting in the B-5 Lot needs to be improved. It was previously reported that there is virtually no light in this

Lot. This remains a problem and the committee again recommends some lighting be installed there.

14. The committee continues to believe the CAB on the Irving Avenue side at the entrance is too dark. The Committee would like additional lighting in this area.

15. It was previously reported that the sign over the Rehab entrance is only partially illuminated and is unsightly. This condition persists and now looks worse than it did last year.

16. The City of Syracuse street light on Niagara Mohawk pole #32 is out and the result is inadequate light on the Adams Street Door.

17. Bldg 49 light on the South Side into the parking lot goes on and off and is in need of repair.