

To: Steven Brady
Vice President for Finance and Management

From: Campus Personal Safety Committee

Subject: Campus Lighting Survey
Conducted November 15, 2005

Date: January 30, 2006

The following are observations and recommendations resulting from the annual survey of Campus by the Campus Personal Safety Committee on November 15, 2005.

Silverman Hall

- Northwest stairway, light outside this exit door has a bad ballast.
- Southeast basement loading dock – outside light is out.

Weiskotten Hall

- Entrance to Weiskotten Hall facing the VA. Lights on the east & west side of the south facing door leading to the south lobby were out.
- On the Irving avenue side of Weiskotten Hall – two of the pole light on the semi-circular sidewalk are out. One south of the main sidewalk to the front door and one to the north.
- Northeast corner of the Library emergency exit door – light is out.
- Along sidewalk leading to the front entrance to Weiskotten Hall, third pole light from the front door is out.
- There is a light on each side of the main entrance to Weiskotten Hall. The south light is out.

Memorial Drive

- Light pole B-9, rear of UH to the north of the 4th flr ramp door, is out
- Light pole just west of the east wing loading dock has a bad ballast. This same light pole has it's access panel missing and wires are exposed.
- Light pole directly adjacent to the walkway from the 5th flr. East wing, south fire door is out.
- East side of the east wing outside the 6th flr. – second pole light from the north – bad ballast.

710 – 714 Irving Ave.

- Lights on the south side of 714 that light the B-5 lot are out.
- Lights on the north side of 710 that light the B-2 lot are out.

CAB

- Court yard/picnic area south of CAB – between CAB & Child Care Center – pole light out.
- Pole light outside Irving Ave. entrance to CAB – bad ballast.
- Wall light over CAB loading dock – bad ballast.
- Light over door to the generator bldg. Irving Ave. side of CAB tennis courts – out.
- EB St. side of CAB – landing outside the main entrance to CAB is dark – lighting needs improvement.

IHP

- Northern most wall light on the east side of IHP – bad ballast.

EB Street

- Pole light A-12 north end of EB St. east side is out.
- Pole lights in front of Clark Towers – north pole light is out.

University Hospital

- Lights above Adams St. door to the north wing of UH are inadequate.
- City pole light #2355 at the northeast corner of Adams & Sarah Loguen St. is out
- Wall light urology wing of UH – northern most light facing the traffic circle is out.
- West side of the traffic circle is poorly lighted. Two pole lights are there but they are both out. The temporary lighting installed during lobby construction help very little.
- Wall light next to the UH exit door on the west side of the south wing used by DOCS to bring inmate/patients into UH is out.

CWB

- 2 middle bays to the warehouse – the west wall light in each bay is out.

City street light on Monroe St. outside Bldg. #49 is out.