



UPSTATE

MEDICAL UNIVERSITY

Materials Management

Clinical Supplies, Materials and Logistics



BD HUBERPLUS → BD MINILOC

BD has made the decision to no longer supply the Port Access Needle HuberPlus safety infusion sets. BD will continue to supply the MiniLock Port Access Needle.

Listed below are the replacement Port Access Needles.

Discontinued: HuberPlus



Replacement: MiniLoc



Lawson	Description		Lawson	Description
61713	HuberPlus 19G X 0.75"	→	61713	MiniLoc Swis 19G X .75"
60656	HuberPlus 20G X 1"	→	60688	MiniLoc Swis 20G X 1"
61712	HuberPlus 20G X 0.5"	→	61712	MiniLoc Swis 20G X .05"
61586	HuberPlus 20G X 0.75	→	60021	MiniLoc Swis 20G X 0.75"
61533	HuberPlus 22G X 1.5"	→	60017	MiniLoc Swis 22G X 1.5"
61532	HuberPlus 22G X 0.75"	→	60018	MiniLoc Swis 22G X 0.75"